





SUGGESTED BASE MACHINE SIZE



Wheeled materials handler:



BASE MACHINE REQUIREMENTS

Two hydraulic services down the boom to operate the grapple open / close and rotate - left and right functions (shear / rotate function)

Grab Open / Close 350 Bar + 100-120 litres / minute oil flow.

Grab Rotate

250 Bar + 60-80 litres / minute oil flow. Please note: This is not standard and may require the pump on the machine to be changed for a higher output version.



2 Two hydraulic functions through the front of chassis of the machine

Clamp Legs Raise / Lower + Open / Close 350 Bar + 100-120 litres / minute oil flow.

Please note: Although some machines can be ordered new with these functions already fitted, standard machines will require the extra services to be installed, consideration should be given to the extra cost of this work when buying a machine. Machines already fitted with the extra hydraulic services to the undercarriage (i.e. a blade service) will be simpler (therefore cheaper) to convert.

J Unbreakable glass protection (Margard) front window




Please note: This is not standard and will need to be fitted to the machine.

SUGGESTED OPTIMAL MACHINE SPECIFICATION



Existing Bulldozer Blade Mounts (To make installation simpler)




Short Dipper Boom & Large dia. Pivot Pins (Short dipper boom allows greater control of the VRS Grab when operating close in to the machine, Large dia. pivot pins - for strength and longevity)



Two-Piece Boom
(Increases rigidity and reduces cost compared to a 3 piece boom)



Quick Coupler on End of Boom Adds Extra Weight (To be used only if required)



Large and Wide Track Frame on Excavators (For optimal stability)

Outriggers on Materials Handlers
(For optimal stability)



CONTACT INFO FOR TECHNICAL ADVICE

KEN COUPLAND

TECHNICAL MANAGER

Tel: 01387 860241 Mobile: 07734 877135 ken@powerhand.com

Parkgate | Dumfries | DG1 3NB

SCOTT ROBERTSON

PRODUCTION MANAGER

Tel: 01387 860241 Mobile: 07584 070048 info@powerhand.com

Parkgate | Dumfries | DG1 3NB

Powerhand has no responsibility as to the performance of the excavator's hydraulic system or the structural adequacy for fitting of the VRS. If there is any doubt the customer should consult the machine manufacturer themselves.

